MUNCIE POWER PRODUCTS, INC.

International Manufacturer of Power Take-Offs and Hydraulic Systems



IMPORTANT INSTALLATION INSTRUCTIONS

INCORRECT FLANGE & BRACKET ORIENTATION WILL ADVERSELY AFFECT EXTENDED SHAFT LIFE AND MAY AFFECT WARRANTY COVERAGE

SEE ATTACHED PICTURES FOR CORRECT FLANGE & BRACKET ORIENTATION FOR THESE SHAFT EXTENSIONS: 49TA4495A, 49TA4506A & 49TA4837A Check the PTO mounting flange orientation against Figure 1. If needed rotate the PTO flange to match Figure 1.

CS10 (A39131) Flange Orientation for Allison 3000 & Left Side Shaft Extension




Figure 1




Figure 2

CS10 Left Side Allison 3000 Bracket Orientation

Check the shaft extension mounting bracket orientation against Figure 3. If needed move the shaft extension bracket to match Figure 3.



Figure 3

If the bracket bolt holes do not align with the transmission bolt holes similar to Figure 4, recheck to make sure all flange and bracket orientations are as shown in Figures 1-3. If misalignment still exists contact Muncie Power Products for further instructions.

