



MUNCIE POWER PRODUCTS

Product Bulletin #00086

Subject: TITAN® MC1 Clutch Pack Changes

Date: Effective April 25, 2020

URL: www.munciepower.com


An inline change is being made to the clutch pack components of the TITAN® MC1 PTO. The clutch spacer plates and friction elements in the TITAN MC1 family of PTOs have now been updated to include the same components as used in the CS24 family of PTOs. There are no changes to the torque ratings of the PTO.

The P/Ns and quantities are as follows.

Friction Elements - 49T33564 (8 pcs)

Spacer Plates - 49T40641 (7 pcs)

The order of the clutch plates is as shown in Figure 1.




Figures 2 and 3 show how to identify the new clutch plates versus the old clutch plates.


WE BUILD
TRUST.



MUNCIE POWER PRODUCTS




49T43128




49T43127

Old Clutch Plates - Figure 2



49T33564



49T40641

New Clutch Plates - Figure 3

These components are compatible with all existing TITAN MC1 PTOs. New clutch plates cannot be combined/intermixed with the old clutch plates.

Service parts updates are in process.

Effective product date 4/25/2020

Contact Muncie Power customer service for more information.

WE BUILD
TRUST.