

# INDOT Omni Plus System

## Scraper - Plumbing Instructions

- 1) Ensure the Scraper Manifold is plumbed in parallel to the Primary Manifold.
- 2) Please refer to the drawing below for instructions to plumb the external relief valve to the WSB port.

