



FA SERIES SOLENOID VALVE REPLACEMENT

Valve Kit 35TK4631A Solenoid with Fittings
(replaces 35T38279)

VALVE REPLACEMENT INSTRUCTIONS:

When replacing 35T38279 solenoid valve with 35T37928, follow the diagram to the right.

The 35T37928 valve does not have access for the temperature sender, but the sender is no longer a requirement of the Muncie or Ford system and can be disconnected.



IN06-03 Printed in the U.S.A.
© Muncie Power Products, Inc. 2006

Muncie Power Products, Inc. Member of the Interpump Hydraulics Group
General Offices and Distribution Center • P.O. Box 548 • Muncie, IN 47308-0548
(765) 284-7721 • FAX (765) 284-6991 • E-mail info@munciepower.com
Web site <http://www.munciepower.com>

Drive Products, Exclusive Agents for Canada, ISO Certified by an Accredited Registrar