



MUNCIE POWER PRODUCTS

Product Bulletin PB00078

Subject: PF4 Pump Changes

Date: October 21, 2019


URL: www.munciepower.com

The capscrew spot face on the PF4 pump rear cover has changed and is slightly smaller and subsequently requires a smaller OD washer. The new washer part number is: 21T64303.

At the same time we have changed to a socket head vs. hex head capscrew. The socket head capscrews are a higher grade material. For the Type 2 pumps, the new capscrew torque is 50-53 ft.lbs. (68-72 Nm).

The new capscrews are black in color and have a new part number: 19T38***SH. These range in lengths of 4.00" to 6.25". i.e. 19T38550SH (5.50 in.). The new capscrew socket heads require an 8mm or 5/16" allen drive.

The new capscrews and washers will be used on both Type 1 and Type 2 PF4 pumps. The torque for the Type 1 pumps will remain the same at the lower 33-35 ft.lbs.



All of these changes have been implemented. The instruction sheet, IN10-07, sent with the PF4-***-16QS*L pumps has been revised to reflect these changes.

Obsolescence

The PF4-107 displacement pumps are now obsolete. This obsolescence is due to no sales over the last 3 years.

WE BUILD
TRUST.