

201 EAST JACKSON STREET POST OFFICE BOX 548 MUNCIE, INDIANA 47308 USA

> 765-284-7721 PHONE 765-751-9506 FAX

## **Product Bulletin #00111**

Subject: PTO Series Obsolescence

Date: January 12, 2023

URL: www.munciepower.com

This product bulletin is to announce the obsolescence of the Muncie Power CS24/25, CS12, CD40, CB6/8, FA62, FR63, and FR3C PTO series. This will be effective immediately.

The Muncie Power CS24/25, CS12, CD40, CB6/8, FA62, FR63, and FR3C series are no longer offered for sale as an assembly. Service parts, which are machined, will be available for the next three (3) years or until inventory is depleted. Other service parts, like bearings, seals, etc., will continue to be available.

The CS24/25 PTO Series can be replaced by the A20 PTO Series. There are some slight differences in PTO output location, so some adjustments to drivelines and/or support bracketry may be required.

The CS12 Series can be replaced by the CS10 Series. Please note, the CS10 Series does have a drag brake on the output shaft that is not present in the CS12 Series.

The CB6/8 Series can typically be replaced by the CS6/8 Series. The CS6/8 Series does not possess a shaft brake in the same sense that the CB6/8 Series possesses, but does include an adjustable drag brake on the output shaft.

There is no direct replacement for the FA62, FR63, or FR3C series. The FR6Q Series may be able to serve as a replacement on some FR3C Series applications, if the torque requirement does not exceed the rating of the FR6Q Series.





These obsoleted series have been removed from the Muncie Power application catalog, including both the printed and electronic versions.

Complete models are no longer available for ordering as of this date.

Contact Muncie Power's customer service for more information.

PTO assemblies: Muncie Power Products will NOT consider parts or units returnable without prior review and authorization.

